



QS Wall Bracket System Installation



Kit Component List

- A. Fitting Mounting Plate (2)
- B. Wall Mounting Plate (2)
- C. 8G x 10mm self tapping screws (4)

Note: Fitting Mounting Plates have a locking screw installed in the top edge

A

B

C

Installation Procedure

- 1 Unpack and check all parts are present as per Kit Component List
- 2 Locate suitable mounting points on the wall
- 3 Mark corresponding mounting points on rear face of fitting by placing fitting bracket at required location and marking through the holes
- 4 Drill 3.5mm Ø holes in face of extrusion to a maximum depth of 5mm
- 5 Mount Fitting Mounting Plates to fitting with the locking screw hole at the top of the bracket and the flat face to the fitting
- 6 Mark position of Wall Mounting Plates on the wall and drill and fix with suitable fixings (note orientation of the Wall Mounting Plate is upside down)
- 7 Feed the power supply cable into the fitting through the cable entry hole and mount the fitting on the Wall Mounting Plates
- 8 Screw the locking screws fully in to position at the top of the brackets to secure the fitting

Note: Locking screws must be removed before attempting to remove the fitting from the brackets

Phone +64 9 827 8980
 Fax +64 9 827 8981
 Address Cnr Bentinck and Drury Streets, New Lynn
 PO Box 15 543, Auckland 0640, New Zealand

www.tlw.co.nz